



Brannan Realty Farm – Topography Map



U.S. Department of Interior Geological Survey Map, 7.5 Minute, Rio Vista Quadrangle
(Not To Scale)

Brannan Realty Farm – Soil Map



<u>Key</u>	<u>Symbol</u>	<u>Description</u>	<u>Capability Unit</u>
	155	Gazwell Mucky Clay	IIIw-10
	169	Laugenour Loam	IIw-2
	201	Rindge Mucky Silt Loam	IIIw-10
	206	Sailboat Silt Loam	IIw-2
	222	Scribner Clay Loam	IIw-2
	232	Valpac Variant Sandy Loam	IIIw-10

Soil Survey of Sacramento County, Issued April 1993, Map Sheet 10